

# TOLEDO AUTO ELECTRIC SERVICE

1804 MONROE STREET P.O. BOX 80039

TOLEDO, OHIO 43608

TOLL-FREE(800) 283-2839 LOCAL (419) 243-7101 FAX (419) 321-1877

SERVING YOU SINCE 1932

[www.taeservice.com](http://www.taeservice.com) EMAIL [tae@taeservice.com](mailto:tae@taeservice.com)



## For Diamond Snow Plows & Meyer Quick Lift E-50, E-60 Snow Plows

W-8991

Replaces: 15727, M2800, MUE-6209, DCM00015, 2869AB, 46-4196, 15689, 82-7852, 8451, AMT0351, 2529AB, 2529AC

12V, CW, Double Ball Bearing, O-Ring Sealed at End Frame

\$95.00

## Snow Plow Motors



## For Fenner Fluid Power, Sno-Way Snow Removal Equipment, Boss Snow Plow w/ Fenner Pump

W-9787

Replaces: D-6000, DCM-0013, T-8789, 1185AC, 1787AC, 520-001, 1931AC, 13850, 25169, P46340, M-3400, FN2-0001N, MUE-6114S, 46-4048, A150265, 222423, AMT0097, 02-1020

12V, CW, Gold Style, 9-Spline, Double Ball Bearing

\$101.00

## For Fisher & Western Snow Plow Motor w/ Oil Seal

Replaces: MKW-4009, MUE-6103, MUE-6111, MUE-7001, 540-002, MM18896, PR2-0068N, DCM0011, M-3000, 50133, 54133, 56058, 56062, 56133, 56398, 56410, 58058, 8501, 58082, 46-2473, 46-2584, 46-3938, 9130450036, 9130450083, A-5819

W-6994

12V, 4-Field Coil, Red Field Case, Oil Seal at D.E., Double Ball Bearing O-ring Sealed at Both Ends

\$93.00

W-8994

12V, 4-Field Coil, Red Field Case Oil Seal at D.E.

\$93.00



## For Meyers E-47 Snow Plow Equipment

WMS-W-8032

Replaces: 8300, 8370, 540-000, 46-2415, M-4000, MKW4007, MGL-4105, T8793, CM6579, MM48826, MM50652, MM50675, 15054, DCM-0003, PR2-0060N, 82-7850, 551046, 551046A, 430-21000, 0222328M048HM, 5055240M030MM, 4882640M030MM

12V, CCW, 3" Dia. Permanent Magnet, Ball Bearing D.E. Frame, Gaskets/O-rings at End Frames, 3/16" Armature Slot

\$57.00

## For Early Western Snow Plow Motor w/ Exposed Drive Slot Shaft

W-8940

Replaces: 1020, 25556, 46-806, 6067, 82-6853, 8570, 540-007, DCM-0012, PR2-0063N, M-2900, MEZ-7002

12V, 4-Field Coil Motor, Red Field Case

\$93.00



## For Northman Snow Plow Equipment

W-8012

Replaces: 11032A, 198684, 46-2482, MGL-4007, MKW-4011

12V, CW, 3" Dia. Permanent Magnet Motor, Ball Bearing D.E. Frame, 1/4" Armature Slot

\$78.00



## For Fenner Fluid Power Pump & Meyer Quick Lift E-57, E-57-H, E-60-H Snow Plows

WMS-W-5692

Replaces: AMJ4739, AMJ-4739, 15829, 15841

12V, CW, Insulated Grd., 2-Terminal Post, Double Ball Bearing, 2-Oval Recesses in Pump Face

\$114.00

## Salt Spreader Motors



## For Meyers, Buyers Salt Spreaders

W-8805

Replaces: M-2100, M-5000, W-8800, 4854420M048HM, HM4854420, HM02223, 485440, 690-060, 0462800108, 9107, LMY0002, 36218, 0202000, 430-21001, 26232A, B422340X6329

\$118.00



## For Western & Fisher Style Salt Spreaders

W-8815

Replaces: 064953, 65061, 65416, 022-064953-7-022, F9524, F9524A, 069616787209, 054-94-1242-0434, 107974490221, 1220182, 1220182H, 1409019, 301220182, 801220182H, 301220182H, 3D1220182H, 3D12201828, 3D1220182D

3" Dia., 8" Motor LG, CW or CCW, 1/2 hp, .500" Shaft Dia., 1-7/8" Shaft LG, 5/16-18 Mtg. Holes

\$262.00



## 12V Universal Shaft Motor

WMS-W-9580FE

Replaces: 71188287-8, 71188287, 9580FE

Many customers are adapting this motor to small aftermarket salt spreaders

3" Dia., 5/16" Shaft Dia., 1.25" Shaft LG

\$26.83



## For Sno-Way 6 & 9 Receiver, 1/2 hp Salt Spreaders

WMS-W-8015

Replaces: 113-0675092046, 96105846, 301217182d, 3d1217182d

CW, 2-Post, Insulated Grd., Double Ball Bearing

\$232.57